

## The Msunduzi River Catchment not quite so nice!



E	F	G	Н		J	K	L	M	N
PMB area Duzi River and Tributary E. coli monitoring									
All results	as <i>E. coli /</i> 100 ml								
		1							
	Sample Site description	19/01/2009	26/01/2009	02/02/2009	09/02/2009	16/02/2009	24/02/2009	02/03/2009	09/03/2009
RMD006	uMsunduze at Caluza Bridge	1400	1790	770	10460	4200	2900	2 140	600
RMD007	uMsunduze below Kwapata	7000	11100	10400	13300	12300	8800	12 000	1600
RMD008	uMsunduze at Edendale Weir	5200	4400	3600	4300	17900	8600	15 000	3600
RSL003	Slangspruit above Duzi confluence	19000	210000	90000	23000	16000	147000	65 000	3000
RMD011	Camps Drift Bridge	1720	3610	1500	3260		900	2 480	5480
RMD013	uMsunduze above Dorpspruit confl	3200	5000	2900	930	54800	5000	4 700	6700
RDS003	Dorpspruit at Polo Fields	5300	2000	2250	2380		2900	6 870	800
RDS004	Townbush Stream at Polo Fields	1500	580	2480	1050		3400	3 000	700
RDS005	Dorpspruit Ohrtmann Road	15000	5000	1600	9800	2900	4200	6 100	9100
RMD014	uMsunduze above Refuse Dump	3500	3900	3100	9300	26100	5900	11 800	6700
RMD015	uMsunduze above Darvill VWWV	2300	5480	3600	1100		15000	9 100	10300
RMD016	uMsunduze U/S Baynespruit	4200	4700	4300	1800	38700	16000	64 900	6100
RBS001	Baynespruit at Greytown Road	16100	34500	219000	22000	12200	51700	78 000	326000
RBS002	Baynespruit	29100	11800	6100	12000	10000	24000	98 000	4000
RMD017	uMsunduze U/S Darvill mat river	3900	2600	3650	1100	17000	22000	141 400	6400
	Darvill eff mat river leg before storm dam						<100		
WDV020	Darvill Final Effluent	400	120	2000	190	300000	1 120 000	1350000	<1000
RMD018	uMsunduze D/S Darvill mat river				900			-	4300
RMD019	uMsunduze Motorcross	2000	2400	8160	1600	61000	194000	141 000	8000
						Doornhoek	98 000		



















## The Msunduzi River Catchment not quite so nice!





















## The Msunduzi River Catchment not quite so nice!





















# The Msunduzi River Catchment not quite so nice!




















w

-

-

-

ī

ėŭ.

m

-

逦

1

-

154

in the

ш

3

WATER: Steps needed to prevent shortages, and recycling is one of them

### Could you drink recycled sewage?

### THIS SHOW SHOW THE

WATE year to the same of the s

the Principal Street St. Street S

The second course when the second sec

The state was true by the

### CONTRACTOR AND PARTY AND ADDRESS OF THE PARTY AND ADDRESS.

Towns of the last of the last

Column Street & Red Ann of Street, Street

oring wastermer to high the Named and Haddell states

THE Appleasure blood field and the field f

100 the is appear to other the party of the

A period production of the

Dies office II in his grants-field in Section realizing named in com-

Two position nations are long to college of the college of the many to the College State of the rall to Committee, which are plifted for Magnagoustime and Challenge of the college (The State of the College of the Col

The proper woulded my Version flood over water proper.

The first dead come would be a little on released to the same of t

Alter among option of the parties of the parties of the control of the parties of

media to comment

this Spaling Loss the Union Statement's Community, programs of Statement and Statement

The expense of an emergement of the posterior of a local body one foreign as a made to prompt with the proper. Techniquities with

REPORTALIMIT

CHUNCH: COLOUREIL FASTER SERVICE TO REVEEL HANDVILLE MINISTRY

# The Msunduzi River Catchment not quite so nice!





DUCT cleanup of the Duzi River, 25 Km Downstream Of PMB

















# The Msunduzi River Catchment not quite so nice!













### How healthy is our water?

Challenges facing our water system have to be dealt with now

In Table Statement Street Control

---

HEE

### MONTROSE: RESIDENTS FEAR WATER SAFETY

MONTROSE residents are concerned that their water may not be fit for consumption.

One resident said the water tastes and smells of chlorine "far stronger than in a swimming pool".

Residents in parts of Dunveira were without water for a large part of yesterday, while a burst pipe was being repaired.

Hays said he was told by workers that the pipe in Ginger Road has been leaking for two weeks

Attempts to get comments from the municipality were unsuccessful. — WR.

